Hydrant Inspection Report

Docket No. 01-0490

ICC Staff Exh. 3.00

System: McHenry Shores Water Company Schedule 3.01

		1997	2001		pg. 1 of 2		
Hydrant #	Location	Gals. per min.	Gals. per min.	Comments			
13	Wellhouse on Hilltop Blvd.	1060	No flow test	a) Repair nozzel cap chains; and	COMPLETED		
				b) Hydrants requires painting.	COMPLETED		
12	Bonita & Beach	1170	1190	a) Hydrant requires painting; and	COMPLETED		
				b) Increase height of hydrant (18" to middle of Cap)			
11	Lially wood 9 Vino Ct		No flow test	Panalas dasa nat wark (Operated by Hydrant value (COMDITTED			
11	Hollywood & Vine St.		NO flow test	Repalce does not work. [Operated by Hydrant valve.] COMPLETED			
10	Vine and Green St.	920	400	a) Repair: Hard to operate [restricted flow];			
				b) Hydrants requires painting; and			
				c) Repair nozzel cap chains.			
15	Biscayne Rd. & Carey	840	880	a) Hydrants requires painting.	COMPLETED		
17	Forrest Rd.	820	840	a) Hydrants requires painting.	COMPLETED		
				b) Increaser hieght of hydrant (18" to middle of cap.)*			
18	Forrest Rd. & Hollywood	890	920	a Hydrants requires painting.	COMPLETED		
25	Pleasant & Bonnie	550	590	a Hydrants requires painting.	COMPLETED		
19	Pleasant & Broadway	550	550	a Hydrants requires painting.	COMPLETED		

Note: No Change from last inspection

Hydrant Inspection Report

Docket No. 01-0490

ICC Staff Exh. 3.00

Schedule 3.01

System: McHenry Shores Water Company pg. 2 of 2

		1997	2001			
Hydrant #	Location	Gals.per min.	Gals.per min.	Comm	nments	
20	Capri - about middle of block	560	No flow test	a) Hydrant requires painting.	COMPLETED	
16	Broadway & Hunter Path	600	600	a) Rpalce hydrant due to crack upper barrel.		
14	Broadway & Vista Terr.	710	790	a) Hydrant requires painting.	COMPLETED	
7	Hilltop & Vista Terr.	710	725	a) Rpalce hydrant due to crack upper ba	arrel.	
8	Still Hill Dr. & near Pearl Ave.	420	400	a) Increase height of hydrant (18" to middle of Cap); and		
				a) Hydrant requires painting.	COMPLETED	
9	Still Hill Dr. & near Riverside Dr.	480	No flow test	a) Hydrant requires painting.	COMPLETED	
				b) Repair hydrant nozzel caps.	COMPLETED	
6	Riverside Dr. & Miller Dr.	480	450	a) Hydrant requires painting.	COMPLETED	
Flushing Valves						
21	Hilltop	20	20	a) Remove copper tubing and replace with hydrant.		
24	3216 Beach	300	200			
22	Pearl & Broadway	420	420			
23	Pearl & Carol	420	420			
27	805 Broadway	400	420			

Note: No Change from last inspection



00896"

MCHENRY WATER P O BOX 189 WONDERLAKE, IL 60097 Residential Customers, please call 1-800-Edison-

00507

Docket No. 01-0490 ICC Staff Exhibit 3.0 Schedule 3.02 (a)

Account Number 0050722006

Payment Amount

Illinding Inhahlumlahallahdad ComEd PO Box 805376 Chicago IL 60680-5376 00000418050003533032

00507 2200 60001 3443

005072200600000000134400000003

Return this portion with your check made payable to ComEd. Please write your account number on your check.

When paying in person, please bring the entire bill.

Page 1 Name

MCHENRY WATER

Service Location

1007 HILLTOP BLVD, MCHENRY

Phone Number

har

0050722006

Account Number Issue Date

10/24/2001

11.5 *	Read Meter	Meter		Reading	Meter Reading				
Meter Information	Date			Type	Previous	Present	Diff	Mult x	Usage
	10/24	093756436 093756436		On Pk kW Tot kWh	ACT ACT	ACT ACT			20.15 5075
_									00.0

current Period

Service from 09/25/2001 to 10/24/2301 - 29 Days \$4.50. Water and Sewage Pumping Service Customer charge 390.98 \$.07704 5.075 kWh X Energy charge 5.075 kWh X 0.00078 3.96 Decommissioning adjustment -0.00396 -20.10 Instrument Funding Charge Credit 5,075 kWh X 5.075 kWh X 0.00396 20.10 Instrument Funding Charge Debit 2.20 .54963% Franchise cost \$399.44 X 16.41 State tax

Total current charges \$418.05